



Geoworks7 – RMMS

Routine Maintenance Management System

The Geoworks7 RMMS Highway Inspection Module allows the user to maintain and report on Routine Maintenance Management System (RMMS) Inspections. Defects identified are linked to the appropriate asset and subsequent repair jobs raised.

The system is graphically based, allowing the user to view and interrogate multiple inspections to help build up a picture of defect occurrences over time. A wide range of Inspection and Analysis reports are available.

Geoworks RMMS Module

Mapping | Inspections | Routes | Regimes | Daily Patrols | Settings | Programme

Sect:0002_M7M8_40:33731: Def#0
Sect:0002_M7M8_41:33732: Def#0
Sect:0002_M7M8_42:33733: Def#1
Sect:0002_M7M8_43:33734: Def#0
Sect:0002_M7M8_44:33735: Def#1
Sect:0002_M7M8_45:33736: Def#0
Sect:0002_M7M8_46:33737: Def#0
Sect:0002_M7M8_47:33738: Def#0
Sect:0002_M7M8_48:33739: Def#0
Sect:0002_M7M8_49:33740: Def#0
Sect:0002_M7M8_50:33741: Def#0
Sect:0002_M7M8_51:33742: Def#1
Def:KC IMWF Ch=388.00 2107

Defect Section Inventory Inspection

Activity KC Kerbs/Edgings & Pre-formed Chann
Defect IMWF Impeded water flow(detritus)
Priority 7 Cat 2.3 Permanent

Defect ID 2107

Location Survey Defect Treat Details

Inspection ID 610
Section 0002_M7M8_51
Location EAST 103E7 to 104E7
Location Between marker posts 104E1 and 104
Chainage 388.00 MP

Assoc Inventory Item

Diagram Number


length 3.000 metres
0.000

Notes Surface water channel gullie covers need cleaning

Mapping View Options

All asset details may be displayed together or individual asset types may be turned on or off as required.

Individual Road Sections may be selected and highlighted on the map.



Defects

Highlighting a defect on the map will display any details of the defect in the Location, Survey, Defect and Treatment tabs.

Defect category types are indicated by colour coded symbols displayed on the map.

For more details, call us on 0161 367 8137
or email sales@steanne.co.uk
www.steanne.co.uk





Geoworks7 – RMMS

RMMS Inspection Patrols and Defect Analysis Reports

Several report options for inspections and outstanding works are available, colour coded for Pending or Overdue status.

Historical inspection and defects data may also be displayed for each section.

Geoworks RMMS MidLink M7/M8 Ltd & CRG Portlaoise Report date: 16 May 2013

Inspection Programme: All Inspection Types No. of inspections: 43

Inspection Type: -

Status	Ref.	Description	Comments	By	Insp No.	Last Inspection date	Interval	Next due date
Overdue	5.7	Safety Inspection		ML	1	02/04/2013 12:30	4 Weeks	30/04/2013
Overdue	6.5	Safety Patrol		ML	2	05/01/2011 11:18	4 Weeks	02/02/2011
Overdue	8.26	Lighting Inspection		ML	10	28/03/2013 11:05	4 Weeks	25/04/2013
Overdue		Litter Inspection		ML	11	22/03/2013 12:17	1 Month	22/04/2013
Pending	9.3	Detailed Inspection		ML	3	28/05/2012 13:38	12 Months	28/05/2013
Overdue	8.2.3	Minor Carriageway Repairs		ML	12	02/05/2012 11:29	52 Weeks	01/05/2013
Pending	8.3.2.1	Footways & Cycle Facilities		ML	13	10/08/2012 10:21	52 Weeks	09/08/2013

Geoworks RMMS Module

Client: M7M8

Road Sections

- 0002_M7M8_28 EAST Boundary past 80E9 to 81E9
- 0002_M7M8_29 EAST 81E9 to 82E9
- 0002_M7M8_30 EAST 82E9 to 83E9
- 0002_M7M8_31 EAST 83E9 to 84E9
- 0002_M7M8_32 EAST 84E9 to 85E9
- 0002_M7M8_33 EAST 85E9 to 86E9
- 0002_M7M8_34 EAST 86E9 to 87E9
- 0002_M7M8_35 EAST 87E9 to 88E9
- 0002_M7M8_36 EAST 88E9 to 89E9
- 0002_M7M8_37 EAST 89E9 to 90E9
- 0002_M7M8_38 EAST 90E9 to 91E9
- 0002_M7M8_39 EAST 91E9 to 92E9
- 0002_M7M8_40 EAST 92E9 to 93E9
- 0002_M7M8_41 EAST 93E9 to 94E9
- 0002_M7M8_42 EAST 94E9 to 95E9
- 0002_M7M8_43 EAST 95E9 to 96E9
- 0002_M7M8_44 EAST 96E9 to 97E9
- 0002_M7M8_45 EAST 97E9 to 98E9
- 0002_M7M8_46 EAST 98E9 to 99E9
- 0002_M7M8_47 EAST 99E9 to 100E9
- 0002_M7M8_48 EAST 100E9 to 101E9
- 0002_M7M8_49 EAST 101E9 to 102E9
- 0002_M7M8_50 EAST 102E9 to 103E7
- 0002_M7M8_51 EAST 103E7 to 104E7
- 0002_M7M8_52 EAST 104E7 to 105E7
- 0002_M7M8_53 EAST 105E7 to 106E7
- 0002_M7M8_54 EAST 106E7 to 107E7
- 0002_M7M8_55 SOUTH 146a8 to 145a8
- 0002_M7M8_56 SOUTH 145a8 to 144a8
- 0002_M7M8_57 SOUTH 144a8 to 143a8
- 0002_M7M8_58 SOUTH 143a8 to 142a8
- 0002_M7M8_59 SOUTH 142a8 to 141a8
- 0002_M7M8_60 SOUTH 141a8 to 140a8
- 0002_M7M8_61 SOUTH 140a8 to 139a8
- 0002_M7M8_62 SOUTH 139a8 to 138a8
- 0002_M7M8_63 SOUTH 138a8 to 137a8

Inspected Sections

Insp Name	Date	Type	Weather	Surface	Dir'n	Def#	Insp	Insp ID	Sect
01271642	27/01/2011	Litter Inspection	FINE	DRY	Normal	3	GRE	407	22219
02031537	02/02/2011	Safety Patrol	FINE	WET	Normal	0	GRE	408	22275
03021646	02/03/2011	Safety Inspection	FINE	DRY	Normal	0	GRE	412	22490
03141417	14/03/2011	Safety Inspection	FINE	DRY	Normal	0	SDU	413	22595
03231403	23/03/2011	Litter Inspection	FINE	DRY	Normal	0	GRE	416	22743
03291547	29/03/2011	Safety Patrol	FINE	WET	Normal	0	GRE	418	22843
04071347	29/03/2011	Safety Patrol	FINE	WET	Normal	0	GRE	420	22973

Defects

Activity	Defect	Inv.	Ch.	Cross Section	Priority	Location
LB	LITB	84.00		Left verge or left edge	Cat 2.1 Permanent	M7/near MP 103E8
LB	OTHR	253.00		Lane 3 or right edge	Cat 2.1 Permanent	104E
LB	LITB	903.00		Left verge or left edge	Cat 2.1 Permanent	104E6

Work Details

Treat	Action	Priority	W/O	Issued	Exp	Cust
*	/CLO CLEAN ONLY(ADD TEXT TO SPECIFY)	Cat 2.1 Permanent	898	11/04/2013 11:11:48	YES	

Mobile Working

Steanne GeoMobile software enables inspection routes to be sent to mobile devices, where any defects may be identified and logged.

Completed inspection data and any logged defects are returned to the Geoworks7 RMMS module.



Steanne Solutions Ltd

Hyde Park House, Cartwright Street, Newton, Hyde, Cheshire, SK14 4EH, England
 Tel: +44(0)161 367 8137 Email: sales@steanne.co.uk Website: www.steanne.co.uk

